TECHNICAL SERVICE BULLETIN

BULLETIN NUMBER: G130/G131 - 006 **05/09/2006**

APPLICABLE MODEL:

GESTETNER – C7528n/C7535n
LANIER – LP332c/LP335c
RICOH – AFICIO CL7200/CL7300
SAVIN – CLP128/CLP135

SUBJECT: CONTROLLER BOARD

GENERAL:

To ensure the heat sink stays properly attached to the controller board, the attachment method for the heat sink on the controller board CPU has been changed. The following updated part information is being issued for all G130/G131 Parts Catalogs. Please update your parts catalog with the following information.



					REFERENCE	
OLD PART NO.	NEW PART NO.	DESCRIPTION	QTY	INT	PAGE	ITEM
G1305791	G1305794	Controller Board – G130	1	-	87	6
G1315791	G1315794	Controller Board – G131	1	-	87	6

UNITS AFFECTED:

All G130/G131 printers listed below and manufactured after the serial numbers provided will have the new style controller boards installed during production.

MODEL NAME	SERIAL NUMBER
Gestetner C7528n Lanier LP332c Ricoh Aficio CL7200 Savin CLP128	Q3751200001
Gestetner C7535n Lanier LP335c Ricoh Aficio CL7300 Savin CLP135	Q3851200001

Copyright © 2006 RICOH Corporation. All rights reserved.